



BH205E Axle Ring- Machined Condition


LH





RH





Only Holes
Difference



LH



RH



No difference in Profile/ Cross section